


MCS-SI16-AO4


SENSOR 1-9




SENSOR 1-10



SENSOR 1-11




SENSOR 1-12




SENSOR 1-13




SENSOR 1-14



SENSOR 1-15



SENSOR 1-16




SENSOR 1-1




SENSOR 1-2



SENSOR 1-3




SENSOR 1-4




SENSOR 1-5





SENSOR 1-6



SENSOR 1-7



SENSOR 1-8



(Do not jumper grounds)

NOTES:

1. Sensors **MUST** use shielded cable and shield must not be broken. The shield must be connected only at the Sensor Input terminal block.
2. Pressure and temperature sensors are available with 20', 40' & 60' of cable.
3. All sensor inputs are 0 to 5vdc.
4. Amp Input sensors are field wired and must be shielded cable. They generate their own voltage and do not require 5vdc from the MCS unit.
5. Digital input sensors are field wired and must be shielded cable. The 5vdc is taken out from the sensor terminal and wired through the switch. The jumper must then be set to digital.

6. Factory wired: _____
Field wired: - - - - -


7. Digital Sensor Jumper :
Analog Sensor Jumper :

	MCS-SI16-AO4 TEMPLATE
CAD Tech	M. Schreiber
Date	10/09/2012
Revision	B(2012-11-08)
Page	1 of 2


MCS SENSOR TEMPLATES

All sensors on Template are wired as Factory wired, if needed to be Field wired change lines to dash lines.


Relay Isolated Digital Input (NO)




Relay Isolated Digital Input (NC)




MCS-CT100/250/300/500/800/1500




MCS-T100/T100-L/T300/T300-H/T300-L




DIGITAL INPUT (NC)




DIGITAL INPUT (NO)




Hanbell Motor Protector (INT69IHB)




Carrier 5K Thermistor




External 0-5VDC Input




MCS-200/500/667




MCS-VOLTAGE




MCS-STATIC-5"B




MCS-STATIC-0.2"B




Three Way RUN/OFF/AUTO Switch




Trane Purge Select Switch




MCS-PT1000




MCS-STATIC-1", 5"



MCS-HUMD



Potentiometer



NOTES:

1. Sensors MUST use shielded cable and shield must not be broken. The shield must be connected only at the Sensor Input terminal block.
2. Pressure and temperature sensors are available with 20', 40' & 60' of cable.
3. All sensor inputs are 0 to 5vdc.
4. Amp Input sensors are field wired and must be shielded cable. They generate their own voltage and do not require 5vdc from the MCS unit.
5. Digital input sensors are field wired and must be shielded cable. The 5vdc is taken out from the sensor terminal and wired through the switch. The jumper must then be set to digital.
6. Factory wired: _____
Field wired: - - - - -
7. Digital Sensor Jumper :
Analog Sensor Jumper :

MCS SENSOR TEMPLATES	
CAD Tech	M. Schreiber
Date	10/09/2012
Revision	B(2012-11-08)
Page	2 of 2