



SOFTWARE RELEASE NOTES

MCS-MAGNUM

Version 9.10F

06/24/2012

Updates from previous versions:

New Features:

1. New refrigeration type R402A has been added.
2. Standardized logic to control hot gas solenoid has been added.
3. Note set point #4, 'SP_HGB_TEMP_CUTIN' and setpoint #5, 'SP_HGB_TEMP_CUTOUT'. If the safety time is greater than zero, it will be used in place of default values of 25% on and 30% off. If used, there is no decimal place; 20 is 20%.
4. Standardized pump down logic has been added.

HVAC SOFTWARE ONLY:

5. Added sub-cooling control CLLC. Same functions as CENT. Also, this option requires the current releases of both config & connect programs. Only difference is in the set points:

	HVAC	CENT
a. SP_CLLC_LEVEL_TARGET	#225	#216
b. SP_CLLC_VALVE_TARGET	#226	# 217
c. SP_CLLC_MAX_ROC	#227	# 218

Any questions regarding this release, contact:

support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2012. Copying or distributing this document is prohibited unless expressly approved by MCS.

Bug Fixes:

1. Communication issues have been resolved.
2. EXV control logic set point #64, EXV ZONE 1, has been expanded to allow specifying when the super heat will be tested for low suction. If used change this set point to TARGET type and use the night setback cell to indicate the super heat value.

HVAC SOFTWARE ONLY:

3. A problem with the Hanbell fixed step compressors with multiple tandem exv circuits has been corrected. It was incorrectly pointing to the liquid line solenoid.

REFR SOFTWARE ONLY:

4. A problem has been corrected when calculating the POWER LOSS DELAY state. If the value in set point #159, POWER LOSS DELAY, time was greater than 9, the unit never came out of this state.

RTU SOFTWARE ONLY:

5. A problem with the Hanbell fixed step compressors with multiple tandem exv circuits has been corrected. It was incorrectly pointing to the liquid line solenoid.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2012. Copying or distributing this document is prohibited unless expressly approved by MCS.