



SOFTWARE RELEASE NOTES

MCS-CONNECT
Version 14.00W
10/15/2013

Updates from previous versions:

New Features:

1. New Sensor type - ATPE500 (153)

Bug Fixes:

1. On the small Demo case occasionally an error is being thrown on auto-startup. This was being caused by the Main UI not being fully initialized before the creation of the Info UI made calls back to Main UI to get screen setups. RESOLUTION - I added a 1 sec delay after the Main UI initialization in the auto start code to give it time to fully load the screen setups.
2. If setpoint frame is not iconified in a workspace when switching to it an exception is being throw initializing the tool tips. RESOLUTION - I added a check to determine if the setpoint table is initialized before adding tool tips.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2013. Copying or distributing this document is prohibited unless expressly approved by MCS.