



SOFTWARE RELEASE NOTES

MCS-CONNECT
Version 8.10U
08/11/2011

Updates from previous versions:

New Features:

1. Added 2 new sensor types "SUBCOOL" and "TRBOCR_FLT".

Bug Fixes:

1. Changed the time when authorization level is checked when adjusting a Setpoint value; now it checks after user enters new value instead of checking before displaying value.
2. Changed "Oil Diff" heading in the Status grid to "PSI Diff".
3. Set default values for '# of decimals' and 'sensor units' for sensor types out of range.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2012. Copying or distributing this document is prohibited unless expressly approved by MCS.