



# SOFTWARE RELEASE NOTES

---

MCS-CONNECT  
Version 9.30I  
05/10/2013

## Updates from previous versions:

### Bug Fixes:

1. Previous change is causing MCS-Connect to blow up when creating AoEeromV12 due to the memory location not being correctly initialized. RESOLUTION - Initialized the array correctly.
2. Grids are not properly updating due to the new methods and etc. not being initialized when the grids are first created. RESOLUTION - Depending on the new settings for the Info Screen I initialized them correctly to update when they are displayed.

Any questions regarding this release, contact:  
[support@mcscontrols.com](mailto:support@mcscontrols.com)

---

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905  
(239)694-0089 FAX: (239)694-0031 [www.mcscontrols.com](http://www.mcscontrols.com)

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2013. Copying or distributing this document is prohibited unless expressly approved by MCS.