


MCS-VOLTAGE-3P

3 Voltage Sensors

Wiring Diagram

MCS-MAGNUM OR MCS-SI16-AO4



Fuse: Part #: 25-027
 600V 1/10 AMP Fast Acting
 Quality: 3

