



SOFTWARE RELEASE NOTES

MCS-CONNECT
Version 14.01J
03/27/2014

Updates from previous versions:

Bug Fixes:

1. Added the new Damper grids to the print to file for RTU SW v14.04 and later.
2. PT Chart was not working. The user could not select a different refrigerant type once the chart was open or use the value calculator. This was due to the value display table having 2 less rows than needed to display the value array causing an exception on initialization preventing the remaining functionality. RESOLUTION - I added 2 more columns to the table to allow the complete value array to load without causing an exception.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2014. Copying or distributing this document is prohibited unless expressly approved by MCS.