



SOFTWARE RELEASE NOTES

MCS-CONNECT
Version 8.10K
04/26/2011

Updates from previous versions:

Bug Fixes:

1. Bug fix to correct Lockout Reset button not clearing alarms caused by User Defined sensors in Loop Water Control (LWC).
2. Bug fix to ensure correct indexing of the Analog Output sequence regardless of type of control board used.
3. Bug fix to remove extra decimal being added when not necessary in the Keypad/Display.
4. Bug fix to correct Bacnet ID in Service Panel when value is between 18101-18109 (was being displayed as 1811-1819).
5. Bug fix to rename Tooltip on Print button (changed to "Print" instead of "Transmit SW").

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2012. Copying or distributing this document is prohibited unless expressly approved by MCS.