



SOFTWARE RELEASE NOTES

MCS-CONNECT
Version 9.30J
05/13/2013

Updates from previous versions:

New Features:

1. Copied all code to add the hide/show option to the RO, AO, and SI grid in MagnumV14Device.

Bug Fixes:

1. The Dehumid enable sensor in MicroMag code was being incorrectly displayed sometimes causing MCS-Connect to stop functioning. This was caused by an incorrect index into the controlling sensor. RESOLUTION - Found the offending bug and eradicated it.
2. Service Panel not functioning for V14 device types. The service panel had not been adjusted to work with V14 code. RESOLUTION - Added code to allow the service panel to detect the V14 cfg type and adjust itself accordingly.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2013. Copying or distributing this document is prohibited unless expressly approved by MCS.