



SOFTWARE RELEASE NOTES

MCS-CONFIG Version 18.00B 2/24/2016

Updates from previous versions:

Bug Fixes:

1. In ALL Magnum cfg types V11 on the SI info screen: If the secondary display type memory location is greater than the amount of display types then an out of range error would occur. This was due to machine data not being loaded. Resolution: Insert a test for this memory location to verify within range before testing against the display type. If out of range then set to 0.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2016. Copying or distributing this document is prohibited unless expressly approved by MCS.