



SOFTWARE RELEASE NOTES

MCS-CONFIG Version 8.10A 08/08/2011

Updates from previous versions:

New Features:

1. Added new sensor type: TurboCor Fault.

Bug Fixes:

1. Tooltip fixes - changed the associated setpoints for refrigeration configs on the Circuit Base and Circuit SI screens. Changed the headclick information window text for the "Manual Defrost Switch" and the "Evap. Suct. Temp." columns on the Circuit SI screen
2. Corrected problem that occurred when the display type is MODBUS and the sensor type selected has 0 decimals (the Multiplier column would change the value from a decimal to an integer when it should not).

REFR ONLY:

3. Made the Ambient Temperature Sensor drop down available On the Refrig Info Screen/General Tab

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2012. Copying or distributing this document is prohibited unless expressly approved by MCS.