



SOFTWARE RELEASE NOTES

MCS-CONFIG
Version 8.10E
08/11/2011

Updates from previous versions:

Bug Fixes:

1. Fixed bug in Relay Output sequence list causing 'Runtime Error 15: type mismatch'.
2. Changed the source code on the SI grid for the Sensor Fault Low and Sensor Fault High values to accept an integer value range of -32767 to 32767 instead of -999 to 9999.
3. Changed the sensor display type TurboCorFault to be treated as a digital sensor type when set to Auto. If set to Manual then it is treated as an analog type and the manual value column is editable.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2012. Copying or distributing this document is prohibited unless expressly approved by MCS.