



SOFTWARE RELEASE NOTES

MCS-CONNECT
Version 14.01D
01/03/2014

Updates from previous versions:

New Features:

1. In V14 software versions adding a new refrigerant type called R114 to the refrigerant type memory locations.

Bug Fixes:

1. In RTU config types V11 and V14 when the Evap Fan Table is initialized it has either 4 or 6 columns depending on the type of fan control. When the Print button is clicked and the Evap Fan Table has only 4 columns an error occurs in the print function that stops the Print to File. Resolution: Add a test to the Evap Fan Table print function that looks at the amount of columns before printing the data that is in the table.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2014. Copying or distributing this document is prohibited unless expressly approved by MCS.