



# SOFTWARE RELEASE NOTES

## MCS-CONNECT Version 17.12.00 3/3/2016

### Updates from previous versions:

#### Bug Fixes:

1. Changed the hard coded delay in the autostart code to instead test if the controller is done with its first refresh before switching to Graphics.
2. The graphics on the 10.2" touchscreen are always showing a scrollbar. This is caused by a sizing issue. RESOLUTION - Changed the width of the main JPanel in the info UI and the size of the Graphics frame to work with the 10.2" touch resolution.
3. The Options Setup UI is oversized for the 10.2" touch. I resized it for all resolutions and eventually will re-factor the Alarm Alerts panel to function differently and not need scroll bars.
4. Changed the functionality of the Alarm Alert Setup in the Options Setup popup. Made it similar to a wizard type group of popups.
5. Modbus and User Defined Sensors are displaying incorrect "divisor" information. RESOLUTION - used the same offset that MCS-Connect was using for the "multiply" and "offset" fields.

Any questions regarding this release, contact:  
[support@mcscontrols.com](mailto:support@mcscontrols.com)

---

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905  
(239)694-0089 FAX: (239)694-0031 [www.mcscontrols.com](http://www.mcscontrols.com)

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2016. Copying or distributing this document is prohibited unless expressly approved by MCS.