

SOFTWARE RELEASE NOTES

MCS-CONNECT Version 18.09.02 03/02/2017

Updates from previous versions:

New Features:

- Added all NUC connect functionality to current version. NUC-Connect will now move forward with all new changes. Installation of NUC connect adds a mcspcn.ini file to allow users to find and connect to NUC Firmware.
- 2. New functions in the Alarm Alerts Menu Items along with new formatting and warning popup.
- 3. Added functionality for new Condenser Adaptive Offset

Bug Fixes:

- 1. The User Defined SI wizard was incorrectly saving the Multiply/Divide/Offset fields. RESOLUTION Added code to format the Multiplier and Offset fields in the User Defined SI wizard to display the number of decimals of the SI after the calculation button is pushed.
- 2. In the status refresh for the graphics Connect was using the wrong field.
- 3. Secondary boards for multi board communication causing problems when no multi board available.
- 4. File chooser bug preventing transmit and receive.
- 5. Finished reformatting the Lockout print by adding a new PRINT tab to lockout popup and added state arrays to the bottom of print.
- 6. In CPM Grid added new chiller state so color renderer for chiller state column to turn background red if in Compressor Off state.
- 7. In the SI Sensor type editor the User Logic wizard is adjusting the divisor when the popup first opens which is incorrect.

Any questions regarding this release, contact: support@mcscontrols.com