



# SOFTWARE RELEASE NOTES

## **MCS-CONNECT** **Version 18.21.21** **08/21/2018**

### **Updates from previous versions:**

#### **New Features:**

1. Added a history saving manager to catch errors in the extended History save
2. Added Alarm Alert checks to Graph screens
3. Added new No Auth security level to setpoints
4. New Evap Approach columns per BWW
5. Added Alarm alerts to the Extended history loop so the messages are still sent if the touchscreen is set up for an extended history

#### **Bug Fixes:**

1. Changed the protocol to connect to our new Mail servers
2. Graphics foreground color usage in editable inputs – Added a new tag to handle this.
3. changing a sensor to user logic type – Now forces the user to set up the user log in before alerting the Magnum
4. Updated RTU Circuit Ram to match firmware changes
5. Fixed Bug in extended Lockout info popup to display correct EXV position
6. Updated the lost communication popup to automatically retry after 15 seconds instead of just staying locked up waiting for a user selection of Retry or Cancel.
7. in extended Alarm lockout popup, the incorrect state was being displayed in RTU based firmware
8. RTU configs without Cond Adjust were trying to display condenser adjust the value. Now checking for a valid sensor or displaying N/A

Any questions regarding this release, contact:  
[support@mcscontrols.com](mailto:support@mcscontrols.com)

---

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905  
(239)694-0089 FAX: (239)694-0031 [www.mcscontrols.com](http://www.mcscontrols.com)

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2018. Copying or distributing this document is prohibited unless expressly approved by MCS.