

MCS-CONNECT Version 8.10P 06/02/2011

Updates from previous versions:

New Features:

1. Added support for new type of Analog Output: "Modbus".

Bug Fixes:

- 1. Fixed bug that caused the Oil Differential column to display incorrect values when the sensor is digital in REV V8 SW.
- 2. Fixed bug that displays the Boiler Panel incorrectly on systems that do not have the boiler control enabled, no longer displaying the panel at all.
- 3. Fixed bug that loaded the Remote Address dropdown list multiple times when disconnecting without restarting MCS-Connect.

Any questions regarding this release, contact: support@mcscontrols.com