



SOFTWARE RELEASE NOTES

MCS-CONNECT
Version 8.10X
09/19/2011

Updates from previous versions:

Bug Fixes:

1. Fixed the "Control on" field (was not checking whether the control was on Control Zone or Voltage) Added a check to refresh correct field based on if config is setup for Control Zone or Voltage.
2. For REFR software, changed MCS-Connects compressor RAM structure to match the MCS-Magnums compressor RAM structure (previously they did not match and this was causing all the compressor fields in the control status grid to display incorrect values) Now all compressor fields display correctly in MCS-Connect.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2012. Copying or distributing this document is prohibited unless expressly approved by MCS.