



SOFTWARE RELEASE NOTES

MCS-MAGNUM **Version 14.01L** **09/16/2013**

Updates from previous versions:

Bug Fixes:

RTU:

1. When in heating mode and the compressor is a heat pump with a VFD did not wait for the last compressor to be at its maximum VFD. Corrected this issue.

Any questions regarding this release, contact:

support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2013. Copying or distributing this document is prohibited unless expressly approved by MCS.