



SOFTWARE RELEASE NOTES

MCS-MAGNUM
Version 14.01V
12/05/2013

Updates from previous versions:

Bug Fixes:

RTU:

1. Corrected the problem when unit does not have an outside air damper, still ran the OAD logic.
2. Added the bypass sensor for the second supply fan. Force the fan to 100%.

Any questions regarding this release, contact:

support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2013. Copying or distributing this document is prohibited unless expressly approved by MCS.