



SOFTWARE RELEASE NOTES

MCS-MAGNUM Version 17.10A 11/03/2014

Updates from previous versions:

New Features:

1. Moved alarm_point_index initialization call.
2. Moved MCS_IO structure from machine_eerom to utility_eerom, and added support for SI16-AO4 boards 5&6.
3. Set bytes in Machine_eerom to fillers.
4. Added new alarm #403 "UPDATED RAM CFG". This alarm will be generated if at power up in the config load function we determine that the copy of the config that is store in the Ram is invalid.
5. Added LOOKUP_TABLE_SI type to get Sensor Units & get Sensor Decimal Shift functions, we were defaulting to spare (No decimal no character).

Bug Fixes:

1. Corrected problem with LOOKUP_TABLE_SI not displaying correctly on LCD.
2. Resolved lost Ethernet port issues with ICMP Redirect Messages

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2015. Copying or distributing this document is prohibited unless expressly approved by MCS.