



SOFTWARE RELEASE NOTES

MCS-MAGNUM **Version 17.12G** **01/07/2015**

Updates from previous versions:

Bug Fixes:

1. Corrected issue with new Comp Lockout Reset Relay - coding using 1 to enable the new feature but it needs to be a zero to enable because all config files have this new control byte set to 0xFF."
2. Reverted "Compile error. Corrected circuit_control3 declaration"
3. Reverted "Add new CMP_RO index for a Lockout RELAY. This Relay will be use to inform the BMS system that there is an active lockout state." We are going to use the CMP_RO Alarm indicator
4. Changed AO_EEPROM to match MCS-Config and MCS-Connect single class definition (not a union).

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2015. Copying or distributing this document is prohibited unless expressly approved by MCS.