



SOFTWARE RELEASE NOTES

MCS-MAGNUM

Version 9.13W

12/02/2013

Updates from previous versions:

Bug Fixes:

1. Problems with lost I/O when RO-8 & SI-16 boards were used. This problem was in REFR software where 7 RO-8 & 8 SI-16 boards were used.

LWC:

2. When the LWC status was accessed from the Magnum, watch dog #99 resets occurred on some units. All units with this problem should be loaded with 09.13-W software. Also corrected the displaying of loops 7 & 8.

Any questions regarding this release, contact:

support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2013. Copying or distributing this document is prohibited unless expressly approved by MCS.