



SOFTWARE RELEASE NOTES

MCS-MICROMAG

Version 4.00Y

05/16/2013

Updates from previous versions:

Bug Fixes:

1. Dehumid enable target memory location was not being initialized properly, not allowing certain configurations to enter dehumidification. Resolution: Properly enabled the memory location, dehumidification works properly now.

Any questions regarding this release, contact:

support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2013. Copying or distributing this document is prohibited unless expressly approved by MCS.