**STRESS POINTS**
Secure the cable to a solid location
using wire ties

Shield Drain
wire connected
to Earth Ground

Create a loop
closest to the
Temperature Sensor
and secure
with wire tie.

+5 RED

GND WHITE

OUTPUT BLACK

**DO NOT BEND OR STRESS
AT THIS CONNECTION**

(A) Mount tip with a 4° up angle or more
(B) Tip needs to be in contact with area to be measured

## Three Conductor Shielded
## Cable #20 AWG

**M**ICRO
**C**ONTROL
**S**YSTEMS

5580 Enterprise Pkwy. Fort Myers, FL 33905 USA
Phone: 239-694-0089 • www.mcscontrols.com
support@mcscontrols.com

# MCS-T300

MCS-T300-REV. 2022-06-03