SOFTWARE RELEASE NOTES

MCS-CONNECT
Version 14.01A
11/20/2013

Updates from previous versions:

Bug Fixes:

1. The new alarm types were throwing exceptions when attempting to be displayed. This was caused by incorrectly using the alarm# as the index into the alarm name array. RESOLUTION - Needed to subtract the initial alarm# to get index.
2. The network interface combo box on the Main UI has blank selections available at the end of it and is being loaded with multiple versions of the same name. RESOLUTION - removed extra rows and ensured that the correct array was being used to initialize the combo box.