Installation Steps:

Shielded Cable
(20,40 or 60 ft. 22 ga. supplied)

Shield drain
wire to GND

RED BLACK SHIELD WHITE

+5   GND   SI

DIGITAL   ANALOG

MCS-X
SUPPLY: 6V
OUTPUT: 0.5
RANGE: 0.5
A=GND B=+

Cap

Washer

Remove Cap

Washer

Washer

Washer

It is recommended that the washer be used in All Applications; however, it is **REQUIRED** when installing on steel fittings.

MCS-X
SUPPLY: 6V
OUTPUT: 0.5
RANGE: 0.5
A=GND B=+

5580 Enterprise Pkwy, Fort Myers, FL 33905 USA
Phone: (239) 694 0089 - Fax: (239) 694 0031
www.mcscontrols.com - support@mcscontrols.com
MCS-Pressure Transducer Wiring Diagram (2015-02-09).dwg

Micro Control Systems