SOFTWARE RELEASE NOTES

MCS-CONNECT
Version 14.01C
12/31/2013

Updates from previous versions:
Bug Fixes:

1. Previous change was incomplete. Resolution: Added another option to display in the P-Ratio column based on compressor type and what it is being controlled on.

2. When an AO was being changed from Manual to Auto the AO value was being set back to 0 and then would modulate back to the Wanted%. Resolution: Added the get routine back to the AO ram class which allowed the correct amount of class members to be accessed.