MCS-CONNECT
Version 17.00F
11/19/2014

Updates from previous versions:

New Features:

1. The Function combo box selected value was being incorrectly initialized with its currently selected value. Single Register selections were being displayed as Multi Register. This was caused by a switch case missing a break. RESOLUTION - I added the missing break statement to the switch.

Bug Fixes:

1. Adding support in XML graphics package for four part animated graphics.