SOFTWARE RELEASE NOTES

MCS-CONNECT
Version 17.00T
03/05/2015

Updates from previous versions:
Bug Fixes:

1. In the new SI and AO grids basic tab the Manual Status column was not changing color based on state. Caused by a missing assignment. RESOLUTION - Added the assignment to each device class.

2. The Receive Cfg file chooser is re-opening after a Receive. RESOLUTION - Added code to ensure the Cancel button was functioning correctly.

3. The transmit file chooser is not opening to the correct directory on the Linux based Touchscreen. This is most likely caused by Linux's case sensitivity. RESOLUTION - Edited the linux path to match the install.

4. The ACU MCS-8 Firmware was not loading in MCS-Connect. This was caused by the addition of the ACU config type to the Magnum Firmware, the test to determine config version was incorrect. RESOLUTION - Adjusted the test to correctly identify MCS-8 ACU firmware.