SOFTWARE RELEASE NOTES

MCS-CONNECT
Version 18.06.02
11/09/2016

Updates from previous versions:
Bug Fixes:

1. Fixed a bug in new graph utility that was displaying incorrect values for 0 and 2 decimal sensors.
2. In the Live Graph wizard I removed the separation of the different SI types in the SI drop down list (Analogs and Digitals). Set it back to show all SIs but added a key to alert user of SI type.

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com