SOFTWARE RELEASE NOTES

MCS-CONNECT
Version 9.20F
03/21/2013

Updates from previous versions:
New Features:

1. Adding the row selection column in MagnumV11 to hide/show rows

Bug Fixes:

1. When printing Magnum Information to a text file the printing of the EXV table was throwing an exception and causing the print to file to stop writing out. This was due to exceeding the array size for # of columns. RESOLUTION - I increased the size of the array to match the # of columns in the EXV table.

2. The Setpoint Time Cell Editor creates a popup that is displaying the wrong character for Lockout and Alarm setpoint types. For these types the display character for the extra columns should always be 'S' for seconds. Currently displaying the same display character of the setpoint. RESOLUTION - checking the setpoint type and making the display character correct based on that.

3. The column names in the AlarmLockoutPopupV12 have a square at the end of them due to the name strings not being trimmed of their null character after Connect receives them from the MicroMag. RESOLUTION - Added a function to remove the null character before adding them to the table.

4. Fixed the SI value column issue with displaying the incorrect options for Mode SW sensor type. It still indexed into the incorrect array. RESOLUTION - Added a check into the initialization of the combo box used in this column to use the correct array for ACU config types.