MCS Release Note

Product Type: MCS-Connect Software Revision: 19.01.14
Release Date: November 25, 2025

_____

Release 19.01.14 - Tuesday, November 25, 2025 Log:

Summary:

- This release fixes a critical RAM sizing configuration for Magnum v14 devices that caused display issues in Connect.

Bug Fix Major:

- Corrected the configured RAM size for Magnum v14 circuit data to the proper v19 layout.
- This resolves Connect display issues that were caused by the incorrect sizing.