



NEWS RELEASE

Product Update Announcement

MCS-MAGNUM HARDWARE

MCS-MAGNUM hardware has been modified and its new revision number is 9.1

- ◆ Hardware modification - Ethernet PHY chip was replaced due to end of life of the original PHY chip by the manufacturer.

FOLLOWING FIRMWARE VERSIONS ARE SUPPORTED

V7:

HVAC 07.03-V
CENT 07.03-V
REFR 07.03-V

V9:

HVAC 09.14-P
CENT 09.14-P
REFR 09.14-P
RTUM 09.14-P
PAO 09.14-P
ACU 09.14-P

V16:

HVAC 16.11-G
CENT 16.11-G
REFR 16.11-G
RTUM 16.11-G
PAO 16.11-G
ACU 16.11-G

V17:

HVAC 17.26-A or greater
CENT 17.26-A or greater
REFR 17.26-A or greater
RTUM 17.26-A or greater
PAO 17.26-A or greater
ACU 17.26-A or greater

NOTE: V17 firmware can be found on the MCS WEBSITE -SUPPORT/MAGNUM FIRMWARE



V16, V9, V7 firmware can be found on MCS WEBSITE/ARCHIVE-left column-search for the version of firmware you need.



Any questions regarding this release, contact sales@mcscontrols.com
Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2018.
Copying or distributing this document is prohibited unless expressly authorized by MCS.

5580 Enterprise Pkwy. Fort Myers, Florida 33905
Office: 239-694-0089 Fax: 239-694-0031
www.mcscontrols.com