



SOFTWARE RELEASE NOTES

MCS-CONNECT
Version 14.00U
10/04/2013

Updates from previous versions:

New Features:

1. In the View Menu, added a Menu Item to Maximize and center all Internal Frames on the Info UI desktop. This will prevent internal frames from being lost out of the viewable area of the desktop and the user being unable to get them.

Bug Fixes:

1. The alarm info print to file was getting stuck in an endless loop due to an exception being thrown and caught when printing from a V11 cfg type Magnum. This was due to the incorrect local variable being used instead of the global. RESOLUTION - Getting the global version of the variable.
2. In the Evap Fan Grid for V14 cfg types the last 2 columns are being incorrectly displayed by data and heading. RESOLUTION - Edited how the Evap Fan grid is displayed removing columns if necessary and making sure the correct info is displayed.
3. The Native Interface function calls were in the incorrect class. Both calls were meant to be made from the Main() function call. RESOLUTION - I moved the calls to the main method.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2013. Copying or distributing this document is prohibited unless expressly approved by MCS.