



SOFTWARE RELEASE NOTES

MCS-CONNECT
Version 14.01I

03/07/2014

Updates from previous versions:

Bug Fixes:

1. The Exhaust grid the in Unit Status Frame was blowing up trying to display the last AO value. The index was not being adjusted for the AOs starting at 0. RESOLUTION - Subtracted one from the index to make sure its value started at 0.
2. The Night setback column is still displaying incorrect values. The issue was due to the Night setback variable being stored as an integer. This was preventing the value from overflowing into the negative. RESOLUTION - I changed the variables' data type.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2014. Copying or distributing this document is prohibited unless expressly approved by MCS.