



SOFTWARE RELEASE NOTES

MCS-CONNECT
Version 15.00C
07/29/2014

Updates from previous versions:

Bug Fixes:

1. The File chooser used to load firmware was not filtering file types correctly causing tech errors in the field. RESOLUTION - Changed File Chooser to newer version that works much better. Changed the chooser for the Transmit and receive config file as well.
2. The Menu items used to reset all points back to AUTO were not setup to work with Mag V11 SW. RESOLUTION - Added code to allow this functionality in V11 SW and also created prompts to warn the user of extensive wait time when changing a lot of points.
3. The heating grid in MicroMag is still displaying incorrectly. The ModGas grid is not being displayed if there is not a heating grid present. RESOLUTION - Fixed the grid to test each grid separately.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2014. Copying or distributing this document is prohibited unless expressly approved by MCS.