

2011/12/21

TB-20111201


**Subject: The cancellation of 1/4" flare connector on motor casing of RC2 series compressor (model: RC2-170~RC2-930A/B, except RC2-180A/B)**

**Description:**

There is one 1/4" flare connector on motor casing of RC2 series compressor (model: RC2-170~RC2-930A/B, except RC2-180A/B). This connector is mainly for backup in its function, and from our survey results most of our customers and end-users seldom use it in chiller unit or in after service. The other three connectors on motor casing (angle valve, refrigerant service valve and liquid injection connector) are sufficient for application. Therefore, we will cancel this 1/4" flare connector on motor casing from 2012 (Compressor S/N: 2EXXXXX) without further notice.

We thank you for your kind attention to this issue and appreciate your continued support on Hanbell products. We will keep providing high-quality products and service to our customers worldwide.

**Difference before and after engineering change:**



No.	Name	No.	Name
1	Angle valve	3	<b>Connector (1/4" flare)</b>
2	Refrigerant service valve	4	Liquid injection connector

2011/12/21

**Before engineering change:**  
RC2-610~930A/B (except RC2-620 A/B)



**After engineering change:**  
RC2-610~930A/B (except RC2-620 A/B)

