

STRESS POINT

Create a loop within a foot of the transducer and secure with wire tie.

Secure the cable to a solid location about three feet from the loop using wire tie.

SHIELD

EARTH GROUND

RED  
BLACK  
WHITE

+5 GND SI

DIGITAL / ANALOG

To unplug PACK-CON Cable:

- A. Lift Tab to release cable from transducer.  
B. Grab back end of connector and pull straight out of transducer.

**DO NOT TWIST OR ANGLE WHEN UNPLUGGING**

- C. Make sure Gray cap remains on end of plug.

Three Conductor  
Shielded Cable  
#20 AWG

**MICRO  
CONTROL  
SYSTEMS**

5580 Enterprise Pkwy. Fort Myers, FL 33905 USA  
Phone: 239-694-0089 • [www.mcsccontrols.com](http://www.mcsccontrols.com)  
[support@mcsccontrols.com](mailto:support@mcsccontrols.com)

**PACK-CON-20M**

MADE IN THE USA

PACK-CON-REV. 2023-12-27

STRESS POINT

Create a loop within a foot of the transducer and secure with wire tie.

Secure the cable to a solid location about three feet from the loop using wire tie.

SHIELD

EARTH  
GROUND

RED  
BLACK  
WHITE

+5 GND SI

DIGITAL / ANALOG

To unplug PACK-CON Cable:

- A.** Lift Tab to release cable from transducer.  
**B.** Grab back end of connector and pull straight out of transducer.

**DO NOT TWIST OR ANGLE  
WHEN UNPLUGGING**

- C.** Make sure Gray cap remains on end of plug.

Three Conductor  
Shielded Cable  
#20 AWG

**MICRO  
CONTROL  
SYSTEMS**

5580 Enterprise Pkwy. Fort Myers, FL 33905 USA  
Phone: 239-694-0089 • [www.mcsccontrols.com](http://www.mcsccontrols.com)  
[support@mcsccontrols.com](mailto:support@mcsccontrols.com)

**PACK-CON-40M**

MADE IN THE USA

PACK-CON-REV. 2023-12-27

STRESS POINT

Create a loop within a foot of the transducer and secure with wire tie.

Secure the cable to a solid location about three feet from the loop using wire tie.

SHIELD

EARTH GROUND

RED  
BLACK  
WHITE

+5 GND SI

DIGITAL / ANALOG

To unplug PACK-CON Cable:

- A. Lift Tab to release cable from transducer.  
B. Grab back end of connector and pull straight out of transducer.

**DO NOT TWIST OR ANGLE WHEN UNPLUGGING**

- C. Make sure Gray cap remains on end of plug.

Three Conductor  
Shielded Cable  
#20 AWG

**MICRO  
CONTROL  
SYSTEMS**

5580 Enterprise Pkwy. Fort Myers, FL 33905 USA  
Phone: 239-694-0089 • [www.mccontrols.com](http://www.mccontrols.com)  
[support@mccontrols.com](mailto:support@mccontrols.com)

**PACK-CON-60M**

MADE IN THE USA

PACK-CON-REV. 2023-12-27

STRESS POINT

Create a loop within a foot of the transducer and secure with wire tie.

Secure the cable to a solid location about three feet from the loop using wire tie.

SHIELD

EARTH GROUND

RED  
BLACK  
WHITE

+5 GND SI

DIGITAL / ANALOG

To unplug PACK-CON Cable:

- A. Lift Tab to release cable from transducer.  
B. Grab back end of connector and pull straight out of transducer.

**DO NOT TWIST OR ANGLE WHEN UNPLUGGING**

- C. Make sure Gray cap remains on end of plug.

Three Conductor  
Shielded Cable  
#20 AWG

**MICRO  
CONTROL  
SYSTEMS**

5580 Enterprise Pkwy. Fort Myers, FL 33905 USA  
Phone: 239-694-0089 • [www.mcsccontrols.com](http://www.mcsccontrols.com)  
[support@mcsccontrols.com](mailto:support@mcsccontrols.com)

**PACK-CON-100M**

MADE IN THE USA

PACK-CON-REV. 2023-12-27

STRESS POINT

Create a loop within a foot of the transducer and secure with wire tie.

Secure the cable to a solid location about three feet from the loop using wire tie.

SHIELD

EARTH GROUND

RED  
BLACK  
WHITE

+5 GND SI

DIGITAL / ANALOG

To unplug PACK-CON Cable:

- A. Lift Tab to release cable from transducer.  
B. Grab back end of connector and pull straight out of transducer.

**DO NOT TWIST OR ANGLE WHEN UNPLUGGING**

- C. Make sure Gray cap remains on end of plug.

Three Conductor  
Shielded Cable  
#20 AWG

**MICRO  
CONTROL  
SYSTEMS**

5580 Enterprise Pkwy. Fort Myers, FL 33905 USA  
Phone: 239-694-0089 • [www.mcsccontrols.com](http://www.mcsccontrols.com)  
[support@mcsccontrols.com](mailto:support@mcsccontrols.com)

**PACK-CON-150M**

MADE IN THE USA

PACK-CON-REV. 2023-12-27