



SOFTWARE RELEASE NOTES

MCS-CONNECT
Version 14.00N
08/06/2013

Updates from previous versions:

Bug Fixes:

1. In MicroMag the Compressor grid in the internal cooling frame is being partially cut off by the split pane divider. RESOLUTION - Increased the value used to space the split pane divider.
2. MCS-Connect is casting into an incorrect device type when auto saving to a text file from the touchscreen when it runs the screen saver in graphics mode. It is casting incorrectly into a Mag V11 device type even if it is a Mag V14 or MicroMag. RESOLUTION - Removed the cast and changed the methods to be abstract methods in the Device class.
3. When clicking the rescan button from the status grid MCS-Connect stops updating and does not rescan. This was caused by a recent change checking the device array with a negative index. RESOLUTION - Added a check to make sure the index is valid before using it to get the selected device.
4. Added support to MCS-Connect for Magnum V14 offline graphs. Prior to this fix any saved offline graph from a V14 Magnum was causing MCS-Connect to show no data.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2013. Copying or distributing this document is prohibited unless expressly approved by MCS.