



SOFTWARE RELEASE NOTES

MCS-CONNECT
Version 14.01H
02/27/2014

Updates from previous versions:

Bug Fixes:

1. The print button in the lockout alarm history popup continues to get hidden on certain resolutions. **RESOLUTION-** Moved the lockout alarm history popup Print button to the top of the window. Also added a time stamp to the print out.
2. The Night Setback column in the setpoint grid is not displaying negative values correctly. This is the same issue we saw with Operands. **RESOLUTION -** Now performing the same check as with the Operands on the Night Setback member to ensure that negative values are displayed correctly.
3. In the Service Frame the action button and corresponding warning popup reference a "Magnum" regardless of controller type. **RESOLUTION -** Changed button's and popup's labels to use "Controller"

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2014. Copying or distributing this document is prohibited unless expressly approved by MCS.