



SOFTWARE RELEASE NOTES

MCS-CONNECT
Version 17.00M
01/28/2015

Updates from previous versions:

New Features:

1. In pump groups, changed the default sensor name in the "Control On" column to "Pump Diff." if group control is set to differential.
2. CENT V17 Firmware only - Changed the centrifugal comp state name from "Surge SPD/VANE" to "SURGE CONTROL". This heading is correct now for both units with and without VFD.
3. Allow the user to set the default RO Table view (either Basic or Advanced). This facilitated the addition of a new tab in the Communication Setup UI, labeled "Tables". I moved all options related to table to this tabs panel.
4. Reorganized the Main UI to be a little more user friendly and logical.

Bug Fixes:

1. In the Pump Group Grid's Target column the decimal place and character being used was incorrect. RESOLUTION - I added code to use the Control on field's decimal place value and character.
2. "Surge SPD/VANE" to "SURGE CONTROL". This heading is correct now for both units with and without VFD.
3. Removed the Circuit flow option for lockout history for REF configs.
4. The Graphic XML Loader was using the incorrect value when looping through xml images to display. RESOLUTION - Changed the code to use the listed # of images instead of the parsed # of images.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2015. Copying or distributing this document is prohibited unless expressly approved by MCS.