



SOFTWARE RELEASE NOTES

MCS-CONNECT
Version 14.01B
12/09/2013

Updates from previous versions:

Bug Fixes:

1. Changed the number of decimal places displayed in the "P-Ratio" column in the circuit state grid from 1 to 2 places.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2013. Copying or distributing this document is prohibited unless expressly approved by MCS.