



SOFTWARE RELEASE NOTES

MCS-CONNECT
Version 17.00I
01/05/2015

Updates from previous versions:

Bug Fixes:

1. Added code to start the transmit and receive file chooser in Details view and sized it.
2. The Alarm popup created from the "ALARM" button was inconsistent in getting the latest data. This was facilitated by the lack of any retries for the info request messages. RESOLUTION - I added 3 retries to the 2 transmit Expect Reply functions in the refresh Alarm History to try and make this function more reliable.
3. In Refrig V14 the defrost time delay field was getting out of range values causing it to display negative time values when converted to a countdown timer. RESOLUTION - Changed the field to an integer which is large enough to store the whole value as a positive.
4. Finished implementing new Swing based Gauges for MCS Graphics.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2015. Copying or distributing this document is prohibited unless expressly approved by MCS.