

SOFTWARE RELEASE NOTES

MCS-CONNECT Version 17.04.00 07/30/2015

Updates from previous versions:

New Features:

- 1. New Gauges and Graphic Widgets
- 2. Adding support for EXV control on Cond Level, includes 2 new States and a column header change.
- 3. Changing a structure in the CPM V17 config. Adding code to match this change. 2 new structures to replace the CoolTowersEeromV17.
- 4. In the MicroMag a Ref Type column was added to Unit Grid.
- 5. Adding the ability to specify the font used in the XML Graphics Button widget.

Bug Fixes:

- 1. Changes made to the Capacity control Grid and Mode Headers to work with the new MHRC cfg type(158). Added MHRC Firmware type to Firmware checks
- 2. Updated the Service Window's RS485 tab to use the correct field to populate the Address combo box.
- 3. In the Circuit Grid the FLA% column was showing erroneous values when not applicable. RESOLUTION-Added a check to match what the Firmware does to verify if a value needs to be displayed.
- 4. Previous change was causing confusion in the field as Techs were unable to tell if a change to the graph interval had been successfully made. RESOLUTION- Updated the history eerom after every Graph Setup save.
- 5. Added the Comp Surging Setpoint alarm to the lockout alarms with extra info list.
- Due to the check for graphics the modbus device type was throwing an exception when getting authorized in the status screen. RESOLUTION -Added a check for that device type to skip the graphics check.
- 7. The test for graphics in the initialize button function is causing issues with pre v11 configs. RESOLUTION-Added a try catch to catch the exception if thrown allowing the buttons to still be initialized.

Any questions regarding this release, contact: support@mcscontrols.com