



SOFTWARE RELEASE NOTES

MCS-CONNECT
Version 17.09.04
1/6/2015

Updates from previous versions:

Bug Fixes:

1. Added a check for an empty string when checking the input tags for secondary graphics points.
2. In GraphicXMLLoader class added checks for multimag's in the device array before displaying any secondary point info. If the specified device is not in the array display NULL in inputs and hide images.
3. V11 LWC Configs are printing Status grid incorrectly. Calculating the # of rows in the LWCTable incorrectly RESOLUTION - Getting the # of rows directly from the table.
4. In the new CPM Firmware the RO user logic popup was being skipped due to a check for config version opening a CPM popup first which bypassed the use logic check.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2016. Copying or distributing this document is prohibited unless expressly approved by MCS.