



SOFTWARE RELEASE NOTES

MCS-CONNECT
Version 9.30C
04/04/2013

Updates from previous versions:

Bug Fixes:

1. The new hide/show columns are causing the index used to get the names of the points in graphing to be off by one. This is causing erroneous data to be displayed in the saved offline graphs and the graph setup UI. RESOLUTION - I added a check for Device type to determine which indexes to use when building the Graph Setup UI and the printing to a text file.
2. Previous bug fix was causing the Auth popup to remain visible after authorization due to the attempted hiding of the buttons when they had yet to be initialized. RESOLUTION - I added a check to determine if the status screen had been initialized yet before attempting to hide the buttons.
3. Micro Mag Service panel is not displaying correct information or sending the correct information to the MicroMag after the user changes the values. RESOLUTION - Adjusted the ServicePanelV12 code to work with the new protocol type and display the correct baud rates for rs232 and rs485.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2013. Copying or distributing this document is prohibited unless expressly approved by MCS.