



SOFTWARE RELEASE NOTES

MCS-CONNECT
Version 9.30K
05/15/2013

Updates from previous versions:

New Features:

1. Adding code to support the new machine types in the MicroMag. So far only made changes for CHL type.
2. Redesigned the Top Menu bar for better understandability and added a new option to Delete saved workspaces. Also adjusted how the View menu opens and displays windows. Using the View menu will now open any window and automatically bring it to the front of the display.

Bug Fixes:

1. In Magnum V14 the Setpoint memory location was not being initialized to the correct size. This caused any attempt to index into the array with the larger size to lead to MCS-Connect to stop functioning. This bug was first noticed in the user logic when trying to load the setpoint list when setpoint was chosen as the operand. RESOLUTION - Corrected the value anywhere it was getting the incorrect size.
2. When changing the value of a Manual AO in a V14(Big Mag) cfg type MCS-Connect was not making the change. This was due to a check for version number that did not include V14. RESOLUTION - Added the necessary software version check.
3. In the new MagV14 Devices the setpoint grid was not displaying setpoints > 230. This was caused by a lack of tool tips in the tool tips array for setpoints 231-255. RESOLUTION - Added place holders in the tooltip memory location for the setpoints 231-255.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2013. Copying or distributing this document is prohibited unless expressly approved by MCS.