

2012/4/30

TN-20120401


Subject: About terminal cover plate painting on RC2 series screw compressor

Description:

We would like to inform you that starting from June 1st, 2012, we will be discontinuing the painting process for the terminal cover plates in our production line. This change is being made in response to updates in our painting process, and as a result, we will provide you with unpainted terminal cover plates moving forward.

After conducting several internal tests, we have confirmed that the unpainted terminal cover plate performs just as effectively as the painted version. There are no insulation issues, and its function remains unchanged.

Difference before and after engineering change (All RC2 series models) :



Please feel free to let us know your thoughts about this potential painting change and we will truly consider your idea before we make the final decision.