

Micro Control Systems

APPLICATION NOTE
APP-099

How To Convert a 0-10Vdc Sensor Input To a 0-5Vdc Input on the MCS-Magnum

Revision History

Date	Author	Description
11/19/14	Daniel Bonessi	Created initial version

In order for the magnum to read a 0-10Vdc input you must install a 100k Ohm ¼ Watt 1% resistor in series as shown below.

